



VIA GIULIO PASTORE, 20
10024 MONCALIERI (TO)
Tel. 011 3400911 - Fax 011 3400921
www.dekra-automotivesolutions.com

CLIENTE:
ALD Automotive Italia S.r.l. a socio unico
VIALE LUCA GAURICO 187
00143 - Roma

DATA PERIZIA 17/04/2025		LOCALITA' ECO PROGRAM FLOTTE SRL , via Nomentana,1111, 161, Roma (RM)											
VEICOLO (MARCA - MODELLO - VERSIONE) STELVIO (PC) 2.2 Turbo Diesel 160cv Business At8 Rwd FP					TARGA GG903JJ		TELAIO ZARPAGLX0M7D15643		1° IMMATRICOLAZ. 20/07/2021				
KM. 101164		COLORE. Grigio Stromboli			TIPO SMALTO METALL/DOPPIO								
CODICE PARTE	VOCI DI DANNO LISTINO RICAMBI AGGIORNATO AL	SR		LA		VE		ME		PREZZO LISTINO	DCMS %	RICAMBI IVA esclusa	
		Diff.	TEMPO	Diff.	TEMPO	Diff.	TEMPO	Diff.	TEMPO				
	Smacchiatura									70,00		70,00	
	Carta di circolazione									150,00		150,00	
	Revisione Ministeriale non verificabile												
	Seconda chiave mancante												
1981	Paraurti ant.	M	1,10	M		M	4,25						
1981	Scomposizione paraurti		1,70										
1935	Parafango ant. SX					L	1,60						
0362	Calotta retrovisore est. SX					L	0,30						
2413	Retrovisore est. regolaz. elettr. SX	S	1,00	S		S				294,04	S17	244,05	
0454	Catarifrangente post. SX	S		S		S				16,16	S17	13,41	
5507	Paraurti post. p/sup.	L	1,00	L		L	2,00						
5507	Scomposizione paraurti		1,50										
1945	Parafango post. DX	L	1,50	L	0,85	L	1,30						
2187	Porta post. DX	M	1,50	M	2,45	M	2,70						
2168	Porta ant. DX	L	0,60			L	1,80						
0362	Calotta retrovisore est. DX					L	0,30						
1935	Parafango ant. DX					L	1,60						
5635	Leva cambio autom. compl.	S		S		S			0,45	496,11	S17	411,77	
TOTALE TEMPI			SR 9,90		LA 3,30		VE 15,85		ME 0,45		TOTALE RICAMBI 889,23		
ORE SUPPLEMENTO DOPPIO STRATO 15 %		2,38		ORE SUPPLEMENTO FINITURA 10 % MAX 3 ORE		1,82		ORE AGGIUNTIVE PER VERNICIATURA		1,60		TOTALE ORE SUPPLEMENTARI 5,80	TOTALE ORE VERNICIATURA 21,65
NOTE Pneumatico ant dx - Pirelli - 235/60/18 - invernale - 4.8 mm Pneumatico ant sx - Pirelli - 235/60/18 - invernale - 4.5 mm Pneumatico post dx - Pirelli - 235/60/18 - invernale - 5 mm Pneumatico post sx - Pirelli - 235/60/18 - invernale - 4.9 mm Veicolo sporco esternamente, Carta di circolazione originale non presente, Periziato con pioggia							RICAMBI		889,23				
							MATER. DI CONSUMO ORE 21,65 €/ORA 12,00		259,80				
							USO DIME		0,00				
							SMALTIMENTO RIFIUTI		25,00				
							MANODOPERA CARR. ORE 34,85 €/ORA 45,00		1568,25				
							MANODOPERA MECC. ORE 0,45 €/ORA 45,00		20,25				
							IMPONIBILE		2762,53				
							IVA		607,76				
							TOTALE COMPLESSIVO		3370,29				
CODICE PERITO		FIRMA			RUOLO N.		FERMO TECNICO GIORNI			FOGLIO			
79					0000		5			1			

Legenda

FF:Forfait

PRM:Promemoria

DE:Difetto esecuzione

GR:Grandine

MAC:Macchiato

NU:Normale usura

SRG:Adesivi



VIA GIULIO PASTORE, 20
10024 MONCALIERI (TO)
Tel. 011 3400911 - Fax 011 3400921
www.dekra-automotivesolutions.com

CUSTOMER:
ALD Automotive Italia S.r.l. a socio unico
VIALE LUCA GAURICO 187
00143 - Roma

APPRAISAL DATE 17/04/2025	LOCATION ECO PROGRAM FLOTTE SRL , via Nomentana,1111, 161, Roma (RM)											
VEHICLE (BRAND - MODEL - VERSION) STELVIO (PC) 2.2 Turbo Diesel 160cv Business At8 Rwd FP					PLATE GG903JJ		CHASSIS ZARPAGLX0M7D15643		1st REGISTRATION. 20/07/2021			
KM. 101164	COLOR. Grigio stromboli			ENAMEL TYPE Metall/doppio								
PART CODE	ITEMS OF DAMAGE SPARE PARTS LIST UPDATED TO	SR		LA		VE		ME		PRICE LIST	DCMS SPARE PARTS % VAT excluded	
		Diff.	TIME	Diff.	TIME	Diff.	TIME	Diff.	TIME			
	Stain removal									70,00		70,00
	Registration certificate									150,00		150,00
	Periodical inspection ministerial not verificabile											
	Second key missing											
1981	Front bumper	M	1,10	M		M	4,25					
1981	Bumper dismantling		1,70									
1935	Front fender Sx					L	1,60					
0362	Ext. rear view mirror shell Sx					L	0,30					
2413	Electrically adjustable ext. rear view mirror Sx	S	1,00	S		S				294,04	S17	244,05
0454	Rear reflector Sx	S		S		S				16,16	S17	13,41
5507	Rear bumper, upper part	L	1,00	L		L	2,00					
5507	Bumper dismantling		1,50									
1945	Rear fender Dx	L	1,50	L	0,85	L	1,30					
2187	Rear door Dx	M	1,50	M	2,45	M	2,70					
2168	Front door Dx	L	0,60			L	1,80					
0362	Ext. rear view mirror shell Dx					L	0,30					
1935	Front fender Dx					L	1,60					
5635	Complete automatic gearbox selector lever	S		S		S			0,45	496,11	S17	411,77
TOTAL TIMES			SR 9,90		LA 3,30		VE 15,85		ME 0,45		TOTAL SPARE PARTS 889,23	
DOUBLE LAYER SUPPLEMENT HOURS 15 % 2,38		FINISHING SUPPLEMENT HOURS 10 % MAX 3 HOURS 1,82		ADDITIONAL HOURS FOR PAINTING 1,60		TOTAL ADDITIONAL HOURS 5,80		TOTAL PAINTING HOURS 21,65				
NOTE Right front tire - Pirelli - 235/60/18 - Winter - 4.8 mm Left front tire - Pirelli - 235/60/18 - Winter - 4.5 mm Right rear tire - Pirelli - 235/60/18 - Winter - 5 mm Left rear tire - Pirelli - 235/60/18 - Winter - 4.9 mm Veicolo sporco esternamente , Paper from circulation originale not present , Appraised with rain							SPARE PARTS		889,23			
							MATER. CONSUMPTION HOURS 21,65€/HOUR 12,00		259,80			
							USE TEMPLATES		0,00			
							WASTING DISPOSAL		25,00			
							LABOR CARR. HOURS 34,85€/HOUR 45,00		1568,25			
							LABOR MECH. HOURS 0,45 €/HOUR 45,00		20,25			
							TAXABLE		2762,53			
							VAT		607,76			
							TOTAL		3370,29			
EXPERT CODE 79	SIGNATURE			ROLE NUMBER 0000		STOP TECHNICIAN DAYS 5			SHEET 1			

Legend

Ff: forfait

Prm: reminder

De: lack of execution

Gr: hail

Mac: stained

Nu: normal wear

Srg: stickers