



VIA GIULIO PASTORE, 20
10024 MONCALIERI (TO)
Tel. 011 3400911 - Fax 011 3400921
www.dekra-automotivesolutions.com

CLIENTE:
ALD Automotive Italia S.r.l. a socio unico
VIALE LUCA GAURICO 187
00143 - Roma

DATA PERIZIA 28/02/2025	LOCALITA' T.F. CAR SERVICE SRL , Via Filippo Pecoraino 21-23, 90124, PALERMO (PA)											
VEICOLO (MARCA - MODELLO - VERSIONE) CITRO?N C4 BlueHdi 130 S&S Feel Pack EAT8 Hatchback 5-door (Euro 6D)						TARGA GG537ZY		TELAIO VR7BBYHZBME056389		1? IMMATRICOLAZ. 27/10/2021		
KM. 142548	COLORE. Natural White			TIPO SMALTO METALL/DOPPIO								
CODICE PARTE	VOCI DI DANNO LISTINO RICAMBI AGGIORNATO AL	SR		LA		VE		ME		PREZZO LISTINO	DCMS %	RICAMBI IVA esclusa
		Diff.	TEMPO	Diff.	TEMPO	Diff.	TEMPO	Diff.	TEMPO			
	Disco ruota anteriore sx danneggiato									80,00		80,00
	Disco ruota anteriore dx danneggiato									80,00		80,00
	Disco ruota posteriore sx danneggiato									80,00		80,00
	Disco ruota posteriore dx danneggiato									80,00		80,00
5003	Paraurti ant. parte sup. primer	L	1,00			L	2,00					
5002	Paraurti ant. parte inf. nero					L	1,00					
5002	Scomposizione paraurti		1,50									
1565	Modanatura lat. paraurti ant. nero					L	0,30					
5507	Paraurti post. p/sup. primer	S	0,80	S		S				382,04	S17	317,09
5507	Scomposizione paraurti		1,00									
5134	Spoiler paraurti post. nero					L	0,50					
	Campagna di richiamo da eseguire									0,01		0,01
TOTALE TEMPI		SR 4,30		LA 0,00		VE 3,80		ME 0,00		TOTALE RICAMBI 637,10		
ORE SUPPLEMENTO DOPPIO STRATO 15 % 0,57		ORE SUPPLEMENTO FINITURA 10 % MAX 3 ORE 0,44		ORE AGGIUNTIVE PER VERNICIATURA 1,60		TOTALE ORE SUPPLEMENTARI 2,61		TOTALE ORE VERNICIATURA 6,41				
NOTE Pneumatico ant dx - Continental - 195/60/18 - multistagionale - 5 mm Pneumatico ant sx - Continental - 195/60/18 - multistagionale - 5 mm Pneumatico post dx - Continental - 195/60/18 - multistagionale - 5 mm Pneumatico post sx - Continental - 195/60/18 - multistagionale - 5 mm Veicolo sporco esternamente, CDC copia conforme, Periziato con tempo sereno						RICAMBI		637,10				
						MATER. DI CONSUMO ORE 6,41 ?/ORA 12,00		76,92				
						USO DIME		0,00				
						SMALTIMENTO RIFIUTI		12,42				
						MANODOPERA CARR. ORE 10,71 ?/ORA 45,00		481,95				
						MANODOPERA MECC. ORE 0,00 ?/ORA 45,00		0,00				
						IMPONIBILE		1208,39				
						IVA		265,85				
						TOTALE COMPLESSIVO		1474,24				
CODICE PERITO 97	FIRMA			RUOLO N. 0000		FERMO TECNICO GIORNI 2			FOGLIO 1			

Legenda

FF:Forfait

PRM:Promemoria

DE:Difetto esecuzione

GR:Grandine

MAC:Macchiato

NU:Normale usura

SRG:Adesivi



VIA GIULIO PASTORE, 20
10024 MONCALIERI (TO)
Tel. 011 3400911 - Fax 011 3400921
www.dekra-automotivesolutions.com

CUSTOMER:
ALD Automotive Italia S.r.l. a socio unico
VIALE LUCA GAURICO 187
00143 - Roma

APPRAISAL DATE 28/02/2025	LOCATION T.F. CAR SERVICE SRL , Via Filippo Pecoraino 21-23, 90124, PALERMO (PA)											
VEHICLE (BRAND - MODEL - VERSION) CITRO?N C4 BlueHdi 130 S&S Feel Pack EAT8 Hatchback 5-door (Euro 6D)						PLATE GG537ZY		CHASSIS VR7BBYHZBME056389		1st REGISTRATION. 27/10/2021		
KM. 142548	COLOR. Natural white			ENAMEL TYPE Metall/doppio								
PART CODE	ITEMS OF DAMAGE SPARE PARTS LIST UPDATED TO	SR		LA		VE		ME		PRICE LIST	DCMS SPARE PARTS % VAT excluded	
		Diff.	TIME	Diff.	TIME	Diff.	TIME	Diff.	TIME			
	Left front wheel damaged									80,00		80,00
	Right front wheel damaged									80,00		80,00
	Left rear wheel damaged									80,00		80,00
	Right rear wheel damaged									80,00		80,00
5003	Paraurti front part sup. primer	L	1,00			L	2,00					
5002	Paraurti front part lower nero					L	1,00					
5002	Bumper dismantling		1,50									
1565	Moulding lat. bumper front nero					L	0,30					
5507	Paraurti rear p/sup. primer	S	0,80	S		S				382,04	S17	317,09
5507	Bumper dismantling		1,00									
5134	Spoiler bumper rear nero					L	0,50					
	Recall campaign to be performed									0,01		0,01
TOTAL TIMES			SR 4,30		LA 0,00		VE 3,80		ME 0,00		TOTAL SPARE PARTS 637,10	
DOUBLE LAYER SUPPLEMENT HOURS 15 % 0,57		FINISHING SUPPLEMENT HOURS 10 % MAX 3 HOURS 0,44		ADDITIONAL HOURS FOR PAINTING 1,60		TOTAL ADDITIONAL HOURS 2,61		TOTAL PAINTING HOURS 6,41				
NOTE Right front tire - Continental - 195/60/18 - Multistagionale - 5 mm Left front tire - Continental - 195/60/18 - Multistagionale - 5 mm Right rear tire - Continental - 195/60/18 - Multistagionale - 5 mm Left rear tire - Continental - 195/60/18 - Multistagionale - 5 mm Veicolo sporco esternamente , Cdc copia compliant , Appraised in clear weather							SPARE PARTS		637,10			
							MATER. CONSUMPTION HOURS 6,41 €/HOUR 12,00		76,92			
							USE TEMPLATES		0,00			
							WASTING DISPOSAL		12,42			
							LABOR CARR. HOURS 10,71€/HOUR 45,00		481,95			
							LABOR MECH. HOURS 0,00 €/HOUR 45,00		0,00			
							TAXABLE		1208,39			
							VAT		265,85			
							TOTAL		1474,24			
EXPERT CODE 97	SIGNATURE			ROLE NUMBER 0000		STOP TECHNICIAN DAYS 2			SHEET 1			

Legend

Ff: forfait

Prm: reminder

De: lack of execution

Gr: hail

Mac: stained

Nu: normal wear

Srg: stickers