



VIA GIULIO PASTORE, 20
10024 MONCALIERI (TO)
Tel. 011 3400911 - Fax 011 3400921
www.dekra-automotivesolutions.com

CLIENTE:
ALD Automotive Italia S.r.l. a socio unico
VIALE LUCA GAURICO 187
00143 - Roma

DATA PERIZIA 06/05/2025	LOCALITA' ECO PROGRAM FLOTTE SRL - POZZUOLI, Via Antiniana,14 G, 80078, Pozzuoli (NA)												
VEICOLO (MARCA - MODELLO - VERSIONE) MERCEDES GLC-CLASS (PC) 200 4MATIC EQ-BOOST PREMIUM AUT. FP						TARGA GJ652JM		TELAIO W1N2539811G064411		1° IMMATRICOLAZ. 09/03/2022			
KM. 52870	COLORE. Grigio Selenite Magn			TIPO SMALTO METALL/DOPPIO									
CODICE PARTE	VOCI DI DANNO LISTINO RICAMBI AGGIORNATO AL	SR		LA		VE		ME		PREZZO LISTINO	DCMS %	RICAMBI IVA esclusa	
		Diff.	TEMPO	Diff.	TEMPO	Diff.	TEMPO	Diff.	TEMPO				
	Pneum. ant sx Danneggiato												
	Pneum. post dx Danneggiato												
	Kit gonfiaggio									100,00		100,00	
	Disco ruota anteriore sx danneggiato									80,00		80,00	
	#PRM# Disco ruota anteriore dx danneggiato												
	#PRM# Disco ruota posteriore sx danneggiato												
	Disco ruota posteriore dx danneggiato									80,00		80,00	
3447	#PRM# Tetto												
0556	#PRM# Cofano ant.												
1918	#PRM# Parabrezza												
1981	Paraurti ant. P/assist. parch. grigio	L	1,30			L	2,20						
1981	Scomposizione paraurti		2,30										
5507	Paraurti post. p/sup. primer	L	1,70	L		L	1,50						
5506	Paraurti post. p/inf.	S		S		S				199,54	S17	165,62	
5506	Scomposizione paraurti		1,50										
2187	Porta post. 04/18> DX	L	0,65	L	0,85	L	1,35						
8661	Fanalino lat. retrovisore est. DX	S	0,20	S		S				81,42	S17	67,58	
	Campagne di richiamo da eseguire									0,01		0,01	
TOTALE TEMPI			SR 7,65		LA 0,85		VE 5,05		ME 0,00		TOTALE RICAMBI 493,21		
ORE SUPPLEMENTO DOPPIO STRATO 15 %		0,76		ORE SUPPLEMENTO FINITURA 10 % MAX 3 ORE		0,58		ORE AGGIUNTIVE PER VERNICIATURA		1,60		TOTALE ORE SUPPLEMENTARI 2,94	TOTALE ORE VERNICIATURA 7,99
NOTE								RICAMBI		493,21			
Pneumatico ant dx - Pirelli - 235/55/19 - estivo - 6.1 mm								MATER. DI CONSUMO					
Pneumatico ant sx - Pirelli - 235/55/19 - estivo - 6.1 mm								ORE 7,99 € /ORA 12,00		95,88			
Pneumatico post dx - Pirelli - 235/55/19 - estivo - 5.5 mm								USO DIME		0,00			
Pneumatico post sx - Pirelli - 235/55/19 - estivo - 7.3 mm								SMALTIMENTO RIFIUTI		15,97			
Veicolo sporco esternamente, Periziato con tempo sereno								MANODOPERA CARR.		742,05			
veicolo sporco si riserva da eventuali graffi, schegge o bolli non visibili								ORE 16,49 € /ORA 45,00					
								MANODOPERA MECC.		0,00			
								ORE 0,00 € /ORA 45,00					
								IMPONIBILE		1347,11			
								IVA		296,36			
								TOTALE COMPLESSIVO		1643,47			
CODICE PERITO		FIRMA			RUOLO N.			FERMO TECNICO GIORNI			FOGLIO		
355					0000			3			1		

Legenda

FF:Forfait

PRM:Promemoria

DE:Difetto esecuzione

GR:Grandine

MAC:Macchiato

NU:Normale usura

SRG:Adesivi



VIA GIULIO PASTORE, 20
10024 MONCALIERI (TO)
Tel. 011 3400911 - Fax 011 3400921
www.dekra-automotivesolutions.com

CUSTOMER:
ALD Automotive Italia S.r.l. a socio unico
VIALE LUCA GAURICO 187
00143 - Roma

APPRAISAL DATE 06/05/2025		LOCATION ECO PROGRAM FLOTTE SRL - POZZUOLI, Via Antiniana,14 G, 80078, Pozzuoli (NA)											
VEHICLE (BRAND - MODEL - VERSION) MERCEDES GLC-CLASS (PC) 200 4MATIC EQ-BOOST PREMIUM AUT. FP						PLATE GJ652JM		CHASSIS W1N2539811G064411		1st REGISTRATION. 09/03/2022			
KM. 52870		COLOR. Grigio selenite magn			ENAMEL TYPE Metall/doppio								
PART CODE	ITEMS OF DAMAGE SPARE PARTS LIST UPDATED TO	SR		LA		VE		ME		PRICE LIST	DCMS SPARE PARTS % VAT excluded		
		Diff.	TIME	Diff.	TIME	Diff.	TIME	Diff.	TIME				
	Tire front left danneggiato												
	Tire rear right danneggiato												
	Tire inflation kit									100,00		100,00	
	Left front wheel damaged									80,00		80,00	
	#PRM# Right front wheel damaged												
	#PRM# Left rear wheel damaged												
	Right rear wheel damaged									80,00		80,00	
3447	#PRM# Roof												
0556	#PRM# Front lid												
1918	#PRM# Windscreen												
1981	Paraurti front p/assist. parch. grigio	L	1,30			L	2,20						
1981	Bumper dismantling		2,30										
5507	Paraurti rear p/sup. primer	L	1,70	L		L	1,50						
5506	Rear bumper, lower part	S		S		S				199,54	S17	165,62	
5506	Bumper dismantling		1,50										
2187	Porta rear 04/18> Dx	L	0,65	L	0,85	L	1,35						
8661	External rear view mirror turn indicator Dx	S	0,20	S		S				81,42	S17	67,58	
	Campagne from richiamo from to execute									0,01		0,01	
TOTAL TIMES				SR 7,65		LA 0,85		VE 5,05		ME 0,00		TOTAL SPARE PARTS 493,21	
DOUBLE LAYER SUPPLEMENT HOURS 15 % 0,76		FINISHING SUPPLEMENT HOURS 10 % MAX 3 HOURS 0,58		ADDITIONAL HOURS FOR PAINTING 1,60		TOTAL ADDITIONAL HOURS 2,94			TOTAL PAINTING HOURS 7,99				
NOTE Right front tire - Pirelli - 235/55/19 - Summer - 6.1 mm Left front tire - Pirelli - 235/55/19 - Summer - 6.1 mm Right rear tire - Pirelli - 235/55/19 - Summer - 5.5 mm Left rear tire - Pirelli - 235/55/19 - Summer - 7.3 mm Veicolo sporco esternamente , Appraised in clear weather veicolo sporco si riserva da eventuali graffi, schegge o bolli non visibili								SPARE PARTS		493,21			
								MATER. CONSUMPTION HOURS 7,99 €/HOUR 12,00		95,88			
								USE TEMPLATES		0,00			
								WASTING DISPOSAL		15,97			
								LABOR CARR. HOURS 16,49€/HOUR 45,00		742,05			
								LABOR MECH. HOURS 0,00 €/HOUR 45,00		0,00			
								TAXABLE		1347,11			
								VAT		296,36			
								TOTAL		1643,47			
EXPERT CODE 355		SIGNATURE			ROLE NUMBER 0000		STOP TECHNICIAN DAYS 3			SHEET 1			

Legend

Ff: forfait

Prm: reminder

De: lack of execution

Gr: hail

Mac: stained

Nu: normal wear

Srg: stickers