



VIA GIULIO PASTORE, 20
10024 MONCALIERI (TO)
Tel. 011 3400911 - Fax 011 3400921
www.dekra-automotivesolutions.com

CLIENTE:
ALD Automotive Italia S.r.l. a socio unico
VIALE LUCA GAURICO 187
00143 - Roma

DATA PERIZIA 13/02/2025		LOCALITA' BRASIELLO CARSERVICE SRL , Via Matilde Serao snc, 80029, SANT'ANTIMO (NA)										
VEICOLO (MARCA - MODELLO - VERSIONE) SMART FORTWO COUP? 70 1.0 52kW superpassion twinamic Coup? 3-door (Euro)						TARGA FZ219HM		TELAIO WME4533421K337297		1° IMMATRICOLAZ. 28/10/2019		
KM. 82424		COLORE. Silver Matt			TIPO SMALTO METALL/DOPPIO							
CODICE PARTE	VOCI DI DANNO LISTINO RICAMBI AGGIORNATO AL	SR		LA		VE		ME		PREZZO LISTINO	DCMS %	RICAMBI IVA esclusa
		Diff.	TEMPO	Diff.	TEMPO	Diff.	TEMPO	Diff.	TEMPO			
	Pneum. ant dx Danneggiato											
	Pneum. post dx Danneggiato											
	Kit gonfiaggio									100,00		100,00
	Disco ruota anteriore sx danneggiato									80,00		80,00
	Disco ruota anteriore dx danneggiato									80,00		80,00
	#PRM# Disco ruota posteriore sx danneggiato											
	Disco ruota posteriore dx danneggiato									80,00		80,00
	Seconda chiave mancante											
4690	Guarnizione ossatura vano porta ant. SX	S		S		S				101,16	S17	83,96
4690	Guarnizione ossatura vano porta ant. DX	S		S		S				90,39	S17	75,02
1918	Parabrezza P/sensore luce/pioggia/a/c aut	S	4,80	S		S				247,90	S17	205,76
1981	Paraurti ant. primer	L	1,30	L		L	1,40					
1981	Scomposizione paraurti		1,20									
1935	Parafango ant. SX	L	0,80	L		L	1,10					
0362	Calotta retrovisore est. grigio alluminio SX					L	0,30					
1877	#PRM# Pannello est. porta ant. primer SX											
1863	Ossatura vano porta con parafango post. SX	L	2,00	L	1,10	L	2,10					
4237	Tappo gancio traino paraurti post. primer	S		S		S				8,48	S17	7,04
1992	Paraurti post. primer	L	0,60	L		L	1,70					
1992	Scomposizione paraurti		0,70									
TOTALE TEMPI		SR		LA		VE		ME		TOTALE RICAMBI		
ORE SUPPLEMENTO DOPPIO STRATO %		ORE SUPPLEMENTO FINITURA % MAX ORE		ORE AGGIUNTIVE PER VERNICIATURA		TOTALE ORE SUPPLEMENTARI				TOTALE ORE VERNICIATURA		
						RICAMBI						
						MATER. DI CONSUMO						
						ORE €/ORA						
						USO DIME						
						SMALTIMENTO RIFIUTI						
						MANODOPERA CARR.						
						ORE €/ORA						
						MANODOPERA MECC.						
ORE €/ORA												
IMPONIBILE												
IVA												
TOTALE COMPLESSIVO												
CODICE PERITO	FIRMA			RUOLO N.		FERMO TECNICO GIORNI				FOGLIO 1		



VIA GIULIO PASTORE, 20
10024 MONCALIERI (TO)
Tel. 011 3400911 - Fax 011 3400921
www.dekra-automotivesolutions.com

CLIENTE:
ALD Automotive Italia S.r.l. a socio unico
VIALE LUCA GAURICO 187
00143 - Roma

DATA PERIZIA 13/02/2025	LOCALITA' BRASIELLO CARSERVICE SRL , Via Matilde Serao snc, 80029, SANT'ANTIMO (NA)											
VEICOLO (MARCA - MODELLO - VERSIONE) SMART FORTWO COUPÃ 70 1.0 52kW superpassion twinamic CoupÃ© 3-door (Eur)						TARGA FZ219HM		TELAIO WME4533421K337297		1ª IMMATRICOLAZ. 28/10/2019		
KM. 82424	COLORE. Silver Matt			TIPO SMALTO METALL/DOPPIO								
CODICE PARTE	VOCI DI DANNO LISTINO RICAMBI AGGIORNATO AL	SR		LA		VE		ME		PREZZO LISTINO	DCMS %	RICAMBI IVA esclusa
		Diff.	TEMPO	Diff.	TEMPO	Diff.	TEMPO	Diff.	TEMPO			
2609	Rivestimento inf. paraurti post. P/pacchetto Sport	S		S		S				88,86	S17	73,75
0868	Fanale post. A led SX	S	0,20	S		S				129,80	S17	107,73
1863	Ossatura vano porta con parafango post. DX	L	2,00	L	1,10	L	2,10					
1877	Pannello est. porta ant. primer DX	L	0,50	L		L	1,40					
0362	Calotta retrovisore est. grigio alluminio DX					L	0,30					
1935	Parafango ant. DX	L	0,80	L		L	1,10					
	Campagna di richiamo da eseguire									0,01		0,01
TOTALE TEMPI		SR 14,90		LA 2,20		VE 11,50		ME 0,00		TOTALE RICAMBI 893,27		
ORE SUPPLEMENTO DOPPIO STRATO 15 % 1,73		ORE SUPPLEMENTO FINITURA 10 % MAX 3 ORE 1,32		ORE AGGIUNTIVE PER VERNICIATURA 1,60		TOTALE ORE SUPPLEMENTARI 4,65		TOTALE ORE VERNICIATURA 16,15				
NOTE Pneumatico ant dx - Continental - 185/50/16 - estivo - 6.1 mm Pneumatico ant sx - Continental - 185/50/16 - estivo - 6.2 mm Pneumatico post dx - Continental - 205/45/16 - estivo - 5.1 mm Pneumatico post sx - Continental - 205/45/16 - estivo - 5.5 mm Veicolo sporco esternamente, Periziato con tempo sereno Veicolo sporco e si riserva da eventuali danni occulti						RICAMBI		893,27				
						MATER. DI CONSUMO ORE 16,15 €/ORA 12,00		193,80				
						USO DIME		0,00				
						SMALTIMENTO RIFIUTI		25,00				
						MANODOPERA CARR. ORE 33,25 €/ORA 30,00		997,50				
						MANODOPERA MECC. ORE 0,00 €/ORA 30,00		0,00				
						IMPONIBILE		2109,57				
						IVA		464,11				
TOTALE COMPLESSIVO		2573,68										
CODICE PERITO 81	FIRMA			RUOLO N. 0000		FERMO TECNICO GIORNI 5			FOGLIO 2			

Legenda

FF:Forfait

PRM:Promemoria

DE:Difetto esecuzione

GR:Grandine

MAC:Macchiato

NU:Normale usura

SRG:Adesivi



VIA GIULIO PASTORE, 20
10024 MONCALIERI (TO)
Tel. 011 3400911 - Fax 011 3400921
www.dekra-automotivesolutions.com

CUSTOMER:
ALD Automotive Italia S.r.l. a socio unico
VIALE LUCA GAURICO 187
00143 - Roma

APPRAISAL DATE 13/02/2025		LOCATION BRASIELLO CARSERVICE SRL , Via Matilde Serao snc, 80029, SANT'ANTIMO (NA)										
VEHICLE (BRAND - MODEL - VERSION) SMART FORTWO COUP? 70 1.0 52kW superpassion twinamic Coup? 3-door (Euro)						PLATE FZ219HM		CHASSIS WME4533421K337297		1st REGISTRATION. 28/10/2019		
KM. 82424		COLOR. Silver matt			ENAMEL TYPE Metall/doppio							
PART CODE	ITEMS OF DAMAGE SPARE PARTS LIST UPDATED TO	SR		LA		VE		ME		PRICE LIST	DCMS SPARE PARTS % VAT excluded	
		Diff.	TIME	Diff.	TIME	Diff.	TIME	Diff.	TIME			
	Tire front right danneggiato											
	Tire rear right danneggiato											
	Tire inflation kit									100,00		100,00
	Left front wheel damaged									80,00		80,00
	Right front wheel damaged									80,00		80,00
	#PRM# Left rear wheel damaged											
	Right rear wheel damaged									80,00		80,00
	Second key missing											
4690	Front door perimeter substructure seal Sx	S		S		S				101,16	S17	83,96
4690	Front door perimeter substructure seal Dx	S		S		S				90,39	S17	75,02
1918	Parabrezza p/sensore luce/pioggia/a/c aut	S	4,80	S		S				247,90	S17	205,76
1981	Front bumper primer	L	1,30	L		L	1,40					
1981	Bumper dismantling		1,20									
1935	Front fender Sx	L	0,80	L		L	1,10					
0362	Shell rearview mirror ext. grigio alluminio Sx					L	0,30					
1877	#PRM# Pannello ext. brings front primer Sx											
1863	Door perimeter substructure with rear fender Sx	L	2,00	L	1,10	L	2,10					
4237	Plug gancio towing bumper rear primer	S		S		S				8,48	S17	7,04
1992	Rear bumper primer	L	0,60	L		L	1,70					
1992	Bumper dismantling		0,70									
TOTAL TIMES		SR		LA		VE		ME		TOTAL SPARE PARTS		
DOUBLE LAYER SUPPLEMENT HOURS %		FINISHING SUPPLEMENT HOURS % MAX HOURS			ADDITIONAL HOURS FOR PAINTING			TOTAL ADDITIONAL HOURS			TOTAL PAINTING HOURS	
						SPARE PARTS						
						MATER. CONSUMPTION						
						HOURS €/HOUR						
						USE TEMPLATES						
						WASTING DISPOSAL						
						LABOR CARR.						
						HOURS €/HOUR						
						LABOR MECH.						
						HOURS €/HOUR						
						TAXABLE						
						VAT						
						TOTAL						
EXPERT CODE		SIGNATURE			ROLE NUMBER		STOP TECHNICIAN DAYS			SHEET 1		



VIA GIULIO PASTORE, 20
10024 MONCALIERI (TO)
Tel. 011 3400911 - Fax 011 3400921
www.dekra-automotivesolutions.com

CUSTOMER:

ALD Automotive Italia S.r.l. a socio unico
VIALE LUCA GAURICO 187
00143 - Roma

APPRAISAL DATE 13/02/2025	LOCATION BRASIELLO CARSERVICE SRL , Via Matilde Serao snc, 80029, SANT'ANTIMO (NA)																							
VEHICLE (BRAND - MODEL - VERSION) SMART FORTWO COUPÃ 70 1.0 52kW superpassion twinamic CoupÃ© 3-door (Eur)					PLATE FZ219HM		CHASSIS WME4533421K337297		1st REGISTRATION. 28/10/2019															
KM. 82424	COLOR. Silver Matt			ENAMEL TYPE METALL/DOPPIO																				
PART CODE	ITEMS OF DAMAGE SPARE PARTS LIST UPDATED TO	SR		LA		VE		ME		PRICE LIST	DCMS SPARE PARTS % VAT excluded													
		Diff.	TIME	Diff.	TIME	Diff.	TIME	Diff.	TIME															
2609	Coating lower bumper rear p/pacchetto sport	S		S		S				88,86	S17	73,75												
0868	Fanale rear a led Sx	S	0,20	S		S				129,80	S17	107,73												
1863	Door perimeter substructure with rear fender Dx	L	2,00	L	1,10	L	2,10																	
1877	Pannello ext. brings front primer Dx	L	0,50	L		L	1,40																	
0362	Shell rearview mirror ext. grigio alluminio Dx					L	0,30																	
1935	Front fender Dx	L	0,80	L		L	1,10																	
	Recall campaign to be performed									0,01		0,01												
TOTAL TIMES					SR 14,90		LA 2,20		VE 11,50		ME 0,00		TOTAL SPARE PARTS 893,27											
DOUBLE LAYER SUPPLEMENT HOURS 15 % 1,73		FINISHING SUPPLEMENT HOURS 10 % MAX 3 HOURS 1,32			ADDITIONAL HOURS FOR PAINTING 1,60			TOTAL ADDITIONAL HOURS 4,65			TOTAL PAINTING HOURS 16,15													
NOTE Right front tire - Continental - 185/50/16 - Summer - 6.1 mm Left front tire - Continental - 185/50/16 - Summer - 6.2 mm Right rear tire - Continental - 205/45/16 - Summer - 5.1 mm Left rear tire - Continental - 205/45/16 - Summer - 5.5 mm Veicolo sporco esternamente , Appraised in clear weather Veicolo sporco e si riserva da eventuali danni occulti										SPARE PARTS		893,27												
										MATER. CONSUMPTION HOURS 16,15€/HOUR 12,00		193,80												
										USE TEMPLATES		0,00												
										WASTING DISPOSAL		25,00												
										LABOR CARR. HOURS 33,25€/HOUR 30,00		997,50												
										LABOR MECH. HOURS 0,00 €/HOUR 30,00		0,00												
										TAXABLE		2109,57												
										VAT		464,11												
										TOTAL		2573,68												
EXPERT CODE 81	SIGNATURE				ROLE NUMBER 0000			STOP TECHNICIAN DAYS 5			SHEET 2													

Legend

Ff: forfait

Prm: reminder

De: lack of execution

Gr: hail

Mac: stained

Nu: normal wear

Srg: stickers