



VIA GIULIO PASTORE, 20
10024 MONCALIERI (TO)
Tel. 011 3400911 - Fax 011 3400921
www.dekra-automotivesolutions.com

CLIENTE:
ALD Automotive Italia S.r.l. a socio unico
VIALE LUCA GAURICO 187
00143 - Roma

DATA PERIZIA 06/05/2025		LOCALITA' FLASH CAR & BOATS SRL GROSSI , Via Ragazzi Del 99 7, 21053, CASTELLANZA (VA)											
VEICOLO (MARCA - MODELLO - VERSIONE) TIGUAN (PC) 2.0 Tdi Scr 140kw Advanced Bmt 4mot Dsg FP						TARGA FY998YN		TELAIO WVGZZZ5NZLW814771		1° IMMATRICOLAZ. 09/10/2019			
KM. 160488		COLORE.		TIPO SMALTO METALL/DOPPIO									
CODICE PARTE	VOCI DI DANNO LISTINO RICAMBI AGGIORNATO AL	SR		LA		VE		ME		PREZZO LISTINO	DCMS %	RICAMBI IVA esclusa	
		Diff.	TEMPO	Diff.	TEMPO	Diff.	TEMPO	Diff.	TEMPO				
	Disco ruota anteriore dx danneggiato									80,00		80,00	
	Disco ruota posteriore sx danneggiato									80,00		80,00	
2168	Porta ant. DX	L		L	0,50	L	0,80						
1513	Modanatura arco passaruota ant. P/sport nero satin DX	S	0,10	S		S				137,20	S17	113,88	
5003	Paraurti ant. parte sup. P/Sport primer	M	1,00	M		M	2,00						
3516	Copertura inf. paraurti ant. P/Offroad Pack grigio	S		S		S				146,93	S17	121,95	
5002	Paraurti ant. parte inf. P/Sport nero satinato	S		S		S				214,31	S17	177,88	
5002	Scomposizione paraurti		2,00										
2275	#PRM# Proiettore Led SX												
0556	Cofano ant.	M	0,50	M	1,30	M	1,90						
1945	Parafango post. SX	L		L	0,50	L	0,80						
1515	Modanatura arco passaruota post. nero sat. SX	S	0,10	S		S				125,24	S17	103,95	
5507	Paraurti post. p/sup. primer	L	1,00	L		L	2,00						
1566	Modanatura lat. paraurti post. cromo lucido SX	S		S		S				62,93	S17	52,23	
5506	Paraurti post. p/inf. P/Sport primer	S		S		S				222,86	S17	184,97	
5506	Scomposizione paraurti		1,50										
5134	Spoiler paraurti post. P/Sport/sens.parc./scar.sx/	S		S		S				193,07	S17	160,25	
2209	Portello post.	M	1,00	M	1,30	M	1,90						
TOTALE TEMPI				SR 7,20		LA 3,60		VE 9,40		ME 0,00		TOTALE RICAMBI 1075,11	
ORE SUPPLEMENTO DOPPIO STRATO 15 % 1,41		ORE SUPPLEMENTO FINITURA 10 % MAX 3 ORE 1,08		ORE AGGIUNTIVE PER VERNICIATURA 1,60		TOTALE ORE SUPPLEMENTARI 4,09		TOTALE ORE VERNICIATURA 13,49					
NOTE Pneumatico ant dx - Pirelli - 235/55/18 - estivo - 3 mm Pneumatico ant sx - Pirelli - 235/55/18 - estivo - 3 mm Pneumatico post dx - Pirelli - 235/55/18 - estivo - 3 mm Pneumatico post sx - Pirelli - 235/55/18 - estivo - 3 mm Periziato con tempo sereno								RICAMBI		1075,11			
								MATER. DI CONSUMO ORE 13,49 €/ORA 12,00		161,88			
								USO DIME		0,00			
								SMALTIMENTO RIFIUTI		25,00			
								MANODOPERA CARR. ORE 24,29 €/ORA 45,00		1093,05			
								MANODOPERA MECC. ORE 0,00 €/ORA 45,00		0,00			
								IMPONIBILE		2355,04			
								IVA		518,11			
								TOTALE COMPLESSIVO		2873,15			
CODICE PERITO 378		FIRMA		RUOLO N. 0000		FERMO TECNICO GIORNI 4		FOGLIO 1					

Legenda

FF:Forfait

PRM:Promemoria

DE:Difetto esecuzione

GR:Grandine

MAC:Macchiato

NU:Normale usura

SRG:Adesivi



VIA GIULIO PASTORE, 20
10024 MONCALIERI (TO)
Tel. 011 3400911 - Fax 011 3400921
www.dekra-automotivesolutions.com

CUSTOMER:
ALD Automotive Italia S.r.l. a socio unico
VIALE LUCA GAURICO 187
00143 - Roma

APPRAISAL DATE 06/05/2025	LOCATION FLASH CAR & BOATS SRL GROSSI , Via Ragazzi Del 99 7, 21053, CASTELLANZA (VA)												
VEHICLE (BRAND - MODEL - VERSION) TIGUAN (PC) 2.0 Tdi Scr 140kw Advanced Bmt 4mot Dsg FP						PLATE FY998YN		CHASSIS WVGZZZ5NZLW814771		1st REGISTRATION. 09/10/2019			
KM. 160488	COLOR.			ENAMEL TYPE Metall/doppio									
PART CODE	ITEMS OF DAMAGE SPARE PARTS LIST UPDATED TO	SR		LA		VE		ME		PRICE LIST	DCMS SPARE PARTS % VAT excluded		
		Diff.	TIME	Diff.	TIME	Diff.	TIME	Diff.	TIME				
	Right front wheel damaged									80,00		80,00	
	Left rear wheel damaged									80,00		80,00	
2168	Front door Dx	L		L	0,50	L	0,80						
1513	Moulding arch wheel arch front p/sport nero satina Dx	S	0,10	S		S				137,20	S17	113,88	
5003	Paraurti front part sup. p/sport primer	M	1,00	M		M	2,00						
3516	Coverage lower bumper front p/offroad pack grigio	S		S		S				146,93	S17	121,95	
5002	Paraurti front part lower p/sport nero satinato	S		S		S				214,31	S17	177,88	
5002	Bumper dismantling		2,00										
2275	#PRM# Proiettore led Sx												
0556	Front lid	M	0,50	M	1,30	M	1,90						
1945	Rear fender Sx	L		L	0,50	L	0,80						
1515	Moulding arch wheel arch rear nero sat. Sx	S	0,10	S		S				125,24	S17	103,95	
5507	Paraurti rear p/sup. primer	L	1,00	L		L	2,00						
1566	Moulding lat. bumper rear cromo lucido Sx	S		S		S				62,93	S17	52,23	
5506	Paraurti rear p/inf. p/sport primer	S		S		S				222,86	S17	184,97	
5506	Bumper dismantling		1,50										
5134	Spoiler bumper rear p/sport/sens.parc./scar.sx/dx	S		S		S				193,07	S17	160,25	
2209	Tailgate	M	1,00	M	1,30	M	1,90						
TOTAL TIMES				SR 7,20		LA 3,60		VE 9,40		ME 0,00		TOTAL SPARE PARTS 1075,11	
DOUBLE LAYER SUPPLEMENT HOURS 15 % 1,41		FINISHING SUPPLEMENT HOURS 10 % MAX 3 HOURS 1,08		ADDITIONAL HOURS FOR PAINTING 1,60		TOTAL ADDITIONAL HOURS 4,09		TOTAL PAINTING HOURS 13,49					
NOTE Right front tire - Pirelli - 235/55/18 - Summer - 3 mm Left front tire - Pirelli - 235/55/18 - Summer - 3 mm Right rear tire - Pirelli - 235/55/18 - Summer - 3 mm Left rear tire - Pirelli - 235/55/18 - Summer - 3 mm Appraised in clear weather								SPARE PARTS		1075,11			
								MATER. CONSUMPTION HOURS 13,49€/HOUR 12,00		161,88			
								USE TEMPLATES		0,00			
								WASTING DISPOSAL		25,00			
								LABOR CARR. HOURS 24,29€/HOUR 45,00		1093,05			
								LABOR MECH. HOURS 0,00 €/HOUR 45,00		0,00			
								TAXABLE		2355,04			
								VAT		518,11			
								TOTAL		2873,15			
EXPERT CODE 378	SIGNATURE			ROLE NUMBER 0000			STOP TECHNICIAN DAYS 4			SHEET 1			

Legend

Ff: forfait

Prm: reminder

De: lack of execution

Gr: hail

Mac: stained

Nu: normal wear

Srg: stickers